1		
Is	1	11
		IJ

AMERICAN INTERNATIONAL INDUSTRIES

2220 GASPAR AVENUE LOS ANGELES, CA 90040 CHEM-TEL: (800) 255-3924

MATERIAL SAFETY DATA SHEET

PRODUCT NAME: FORMULA:	Gigi Slow Grow 30-5473				DATE: REV.	4/2/2004 NEW
Section 1. Materia	al Identification an	d Inform	ation			
Hazardous Ingredien	te.					
nazardodo mgroaion	Componer	nt	CAS #	%	TOXICO	DLOGICAL DATA
	No Hazardous Ing	gredients				
Section 2. Physic	cal / Chemical Cha	racterist	ics			
Boiling Point:	N/A		Specific Gravity:	1.00		
Vapor Pressure:	N/A		(H ₂ O =1)			
(mm Hg and Tempera	ture)		Melting Point:	N/A		
Vapor Density: (Air = 1)	N/A		Evaporation Rate: (NAB = 1)	N/A		
Solubility in Water:	Negligible		Water Reactive:	N/A		
Appearance:	White Lotion		% Volatile:	N/A		
Odor:	Herbal Fragrance		(by weight)			
Section 3. Fire an	nd Explosion Haza	rd Data				
Flash Point and Meth Auto-Ignition Tempe	rature:	N/A N/A				
Flammability Limits i	in Air % by Volume:	LEL: UEL:	N/A N/A			
Extinguisher Media:			ray, foam, dry chemic	al or car	hon diovide	
Special Fire Fighting Procedures:			ers should wear full pr			f contained
epecial in e i ignilig		-	apparatus.		souring and ser	roomanica
Unusual Fire and Ex	plosion Hazards:					
Section 4. Reacti	vity Hazard Data					
Stability: Incompatibility (Mate	☑ Stable erials to Avoid): N/A		Unstable			
Hazardous Decompo						

Silicon dioxide, carbon dioxide, and traces of incompletely burned carbon products.

Hazardous Polymerization:

□ May Occur ☑ Will Not Occur

AMERICAN INTERNATIONAL INDUSTRIES

2220 GASPAR AVENUE LOS ANGELES, CA 90040 CHEM-TEL: (800) 255-3924

MATERIAL SAFETY DATA SHEET

PRODUCT NAME: FORMULA:	Gigi Slow Grow 30-5473			ATE: EV.	4/2/2004 NEW	
Section 5. Health	h Hazard Data					
Primary Routes of E	ntry:					
•	Inhalation	Skin Absorption	Ingestion	🗖 Eye	e Contact	
Carcinogen Listed In	า:					
	🗖 NTP	IARC Monograph	🗆 OSHA	☑ Not Listed		
Health Hazards (Res	ulting From Misuse	or Overexposure):				
Medical Conditions Emergency First Aic	contact may irritate Generally Aggravate Allergy to enzyme p				-	
Linergency Trist Ait	Eye Contact:	Flush with plenty of water for at burning sensation develop get n			ss, itching, or	
	Skin Contact:	Wash material off with plenty of soap and water. If redness, itching. or burning sensation develops, get medical attention.				
	Inhalation:	Remove person to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen and get medical attention.				
		Give one or two glasses of water to drink. If gastrointestinal symptoms develop, seek medical attention. Do not induce vomiting unless directed by a physician.				

Section 6. Control and Protective Measures

Respiratory Protections (Specific Type): No special procedure. No special procedure. Protective Gloves: Rubber or vinyl. Eye Protection: Use proper protection - safety glasses as a minimum. Ventilation to be Used: Image: Description of the transformer of the tr

Section 7. Precautions for Safe Handling and Use / Leak Procedures

Steps to be Taken if Material is Spilled or Released:

Use absorbent material to collect and contain for salvage or disposal. Remove all source of ignition and wear proper protection equipment.



AMERICAN INTERNATIONAL INDUSTRIES

2220 GASPAR AVENUE LOS ANGELES, CA 90040 CHEM-TEL: (800) 255-3924

MATERIAL SAFETY DATA SHEET

PRODUCT NAME:	Gigi Slow Grow	DATE:	4/2/2004
FORMULA:	30-5473	REV.	NEW

Waste Disposal Methods:

Observe all federal, state, and local regulations regarding waste disposal.

Precautions to be taken in Handling and Storing:

Store in cool, dry place. Do not expose to light or heat. Wear safety spectacles and gauntlets

when handling. Temperature precautions; do not exceed 100°F, do not freeze (under 33°F.)

Other Precautions and/or Special Hazards:

None